## Oil Field Environmental Incident Summary

**Responsible Party:** Rugged West Services LLC **Well Operator:** ENDURO OPERATING, LLC

Well Name:

Field Name: Well File #: 0

Date Incident: 10/7/2013 Time Incident: 15:30 Facility ID Number:

County: WILLIAMS Twp: 158 Rng: 95 Sec: 6 Qtr: SE SW

Location Description:

Submitted By: Bruce Erickson Received By:

Contact Person: Bruce Erickson

PO Box 729

Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: Unknown

	Spillea	Units	Recovered	Units	
Oil	8	barrels	8	barrels	
Brine	0	barrels	0	barrels	
Other	0	barrels	0	barrels	

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Followup

**Units** 

## Potential Environmental Impacts:

Minimal-This is a high paraffin oil and solidified as it spread out on the location.

## Action Taken or Planned:

Spill was contained on site with absorbent diaper and snakes.

Wastes Disposal Location: Garner Environmental is doing the clean up and IHD will received the

contaminated soil.

Agencies Involved:

**Updates** 

Date: 11/8/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location, according to the report.